



Driginal post set 1821 by Laughlin... 10" beech was the corner tree, with witnesses 18" sugar maple N 33 e 18 links. Legal by Wilson 8-1854 per Lawrence Township Legal Survey Book pg. 10 called monumented with stone. No witness given. Legal by Voorhis 6-1869 per Lawrence Township Legal Survey Book pg. 34 called corner no notes nor witnesses. Survey did show distances across entire S line of 17-17-5. Fortner 5-21-75 called stone 1" down. Cripe 5-74 Job#75005-10100 "Masthead plat" called stone found. 5-75 was redrawn. Excavated 6-21-82 per plat info. 1'x1" hole was dug 36" deep. Railroad spike at surface only marker found. No stone found. Harrison set flush. 12" deep asphalt patch finished the hole. Re-tied 2-3-94 by Vilcoxen. Re-tied 1-14-2000 by Kiste.

## HC752002

REF.	DISTANCE	DESCRIPTION
1.	14.55′	Cut 'x' SE corner of storm inlet
2.	52.85′	Copperweld in Seaward Lane
3,	33,95′	Cut 'x' W-rim of manhole in asphalt to drive #8613
4.	8.21′	Cut 'x' in NE corner of storm inlet
5.	81.63'	C/L C/L copperweld set Seaward Court